

FIG. 1





FIG. 2


| BIT NO. | DIS/DTC  | DCS                                      |
|---------|--|--|
| X       | PRESENCE/ABSENCE OF BOTH-SIDE RECORDING FUNCTION (ALTERNATE MODE)  | BOTH-SIDE TRANSMISSION (ALTERNATE MODE)  |
| X+1     | PRESENCE/ABSENCE OF BOTH-SIDE RECORDING FUNCTION (CONTINUOUS MODE) | BOTH-SIDE TRANSMISSION (CONTINUOUS MODE) |


FIG. 3


|      |         |         |     |    |    |    |        |             |                  |     |      |
|------|---------|---------|-----|----|----|----|--------|-------------|------------------|-----|------|
| FLAG | ADDRESS | CONTROL | FCF | PC | BC | FC | LENGTH | PAGE NUMBER | PAGE INFORMATION | FCS | FLAG |
|------|---------|---------|-----|----|----|----|--------|-------------|------------------|-----|------|

ONLY IN ECM

**FIG. 4**

**FIG. 5**

**FIG. 6**

**FIG. 7**

*FIG. 8*

| ONE-TOUCH DIAL | ADDRESS      | TIMER TRANSMISSION |
|----------------|--------------|--------------------|
| 01             | 03-3111-1111 | 22:00              |


**FIG. 9**



FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14

